



Lab & Rad Safety Newsletter



Alan Watts
Radiation Safety Officer

In This Issue:

-  Instruction Concerning Risks From Occupational Radiation Exposure.....pg.1-3
-  The History of Radiation Safety.....pg.4

 = Required

 = Optional



INSTRUCTION CONCERNING RISKS FROM OCCUPATIONAL RADIATION EXPOSURE

1. What is meant by ALARA?

ALARA means “as low as is reasonably achievable.” In addition to providing an upper limit on an individual’s permissible radiation dose, the NRC requires that its licensees establish radiation protection programs and use procedures and engineering controls to achieve occupational doses, and doses to the public, as far below the limits as is reasonably achievable. “Reasonably achievable” also means “to the extent practicable.” What is practicable depends on the purpose of the job, the state of technology, the costs for averting doses, and the benefits. Although implementation of the ALARA principle is a required integral part of each licensee’s radiation protection program, it does not mean that each radiation exposure must be kept to an absolute minimum, but rather that “reasonable” efforts must be made to avert dose. In practice, ALARA includes planning tasks involving radiation exposure so as to reduce dose to individual workers and the work group. There are several ways to control radiation doses, e.g., limiting the time in radiation areas, maintaining distance from sources of radiation, and providing shielding of radiation sources to reduce dose. The use of engineering controls, from the design of facilities and equipment to the actual set-up and conduct of work activities, is also an important element of the ALARA concept.

An ALARA analysis should be used in determining whether the use of respiratory protection is advisable. In evaluating whether or not to use respirators, the goal should be to achieve the optimal sum of external and internal doses. For example, the use of respirators can lead to increased work time within radiation areas, which increases external dose. The advantage of using respirators to reduce internal exposure must be evaluated against the increased external exposure and related stresses caused by the use of respirators. Heat stress, reduced visibility, and reduced communication associated with the use of respirators could expose a worker to far greater risks than are associated with the internal dose avoided by use of the respirator. To the extent practical, engineering controls, such as containments and ventilation systems, should be used to reduce workplace airborne radioactive materials.

2. How can we compare the risk of cancer from radiation to other kinds of health risks?

One way to make these comparisons is to compare the average number of days of life expectancy lost because of the effects associated with each particular health risk. Estimates are calculated by looking at a large number of persons, recording the age when death occurs from specific causes, and estimating the average number of days of life lost as a result of these early deaths. The total number of days of life lost is then averaged over the total observed group. Several studies have compared the average days of life lost from exposure to radiation with the number of days lost as a result of being exposed to other health risks. The word “average” is important because an individual who gets cancer loses about 15 years of life expectancy, while his or her coworkers do not suffer any loss. Some representative numbers are presented in Table 1. For categories of NRC-regulated industries with larger doses, the average measurable occupational dose in 1993 was 0.31 rem (0.0031 Sv). A simple calculation based on the article by Cohen and Lee (Ref.10) shows that 0.3 rem (0.003 Sv) per year from age 18 to 65 results in an average loss of 15 days. These estimates indicate that the health risks from occupational radiation exposure are smaller than the risks associated with many other events or activities we encounter and accept in normal day-to-day activities. It is also useful to compare the estimated average number of days of life lost from occupational exposure to radiation with the number of days lost as a result of working in several types of industries. Table 2 shows average days of life expectancy lost as a result of fatal work-related accidents. Table 2 does not include non-accident types of occupational risks such as occupational disease and stress because the data are not available. These comparisons are not ideal because we are comparing the possible effects of chronic exposure to radiation to different kinds of risk such as accidental death, in which death is inevitable if the event occurs. This is the best we can do because good data are not available on chronic exposure to other workplace carcinogens. Also, the estimates of loss of life expectancy for workers from radiation-induced cancer do not take into consideration the competing effect on the life expectancy of the workers from industrial accidents.

Table 1 Estimated Loss of Life Expectancy from Health Risks*

<i>Health Risk</i>	<i>Estimate of Life Expectancy Lost (average)</i>
Smoking 20 cigarettes a day	6 years
Overweight (by 15%)	2 years
Alcohol consumption (U.S. average)	1 year
All accidents combined	1 year
Motor vehicle accidents	207 days
Home accidents	74 days
Drowning	24 days
All natural hazards (earthquake, lightning, flood, etc.)	7 days
Medical radiation	6 days
Occupational Exposure	
0.3 rem/y from age 18 to 65	15 days
1 rem/y from age 18 to 65	51 days


*Adapted from Reference 10.

Table 2 Estimated Loss of Life Expectancy from Industrial Accidents*

<i>Industry Type</i>	<i>Estimated Days of Life Expectancy Lost (Average)</i>
All industries	60
Agriculture	320
Construction	227
Mining and Quarrying	167
Transportation and Public Utilities	160
Government	60
Manufacturing	40
Trade	27
Services	27


*Adapted from Reference 10.

➤ The History of Radiation Safety



These questions and answers for risks from occupational radiation exposure will continue with subsequent newsletters

Stay tuned for a continuation of the risk information in the next newsletter!



Who you gonna call? Radiation Safety Contacts

Name	Office	Cell
OUPD	593-1911	
Alan Watts	593-4176	740-517-5075
Ricardo Gaytan	597-2950	956-740-5900
David Schleiter	593-1662	740-591-0557
David Ingram	593-1705	740-707-5362